


Building Completion & Building Safety Certificate

Considering the request of Prinicipal, Pali Academic Institution, Ward No. 03 At Post Bisoni, Tahsil Lanji Distt.- Balaghat - 481222, Madhya Pradesh the building was inspected by undersigned along with Akshay Maxavi (Sub-Engineer PWD, Lanji) JE on dated 11/11/2022..... It was found from visual inspection that the present condition of the building is satisfactory and the building seems to be safe for the purpose of running the School. So, the certificate regarding the building safety is hereby issued which will be valid for one year up to 2035.....


Sub-Engineer
MPPWD, Lanji


Sub-Divisional Engineer
P.W.D. Sub Dn.Lanji
Distt.- Balaghat

Endst No. 362.....

Dated 17/11/2022.....

Copy of above is forwarded to the following for information and necessary action:

1. The Principal of Pali Academic Institution, At Post Bisoni (Lanji), Distt. Balaghat (M.P.) 481222